



















<p>注意事項 燈具安裝請詳細閱讀以下重要事項： 1. 燈具安裝、維護前，必須切斷電源，以防觸電！ 2. 為確保安全，請委託有經驗的電氣專業人員負責安裝維修及保養。 3. 如燈具發生異常現象，請迅速切斷電源，並請專業人員進行處理。</p>  	<p>1.</p> 	<p>2.</p>  <p>2. 取下燈具前罩部分。</p>	<p>4.</p>  <p>4. 將預埋框放入挖孔內並與挖孔對齊。</p>
<p>5.</p> 	<p>6.</p> <p>扭力: 3-3.5kgf.cm</p>  <p>輸入 輸出</p>	<p>3.</p>  <p>3. 選擇合適工具將預埋件取出。</p>	<p>7.</p>  <p>7. 將前罩卡入燈具內。</p> <p>8.</p>  <p>8. 完成安裝，打開電源。</p> <div data-bbox="1556 941 2128 1332"> <p>A</p>  <p>將燈頭拉至末端，握住外框以避免燈具從天花板脫落。</p> <p>B</p>  <p>傾斜並旋轉至所需位置。</p> <p>355° 45°</p> <p>當燈頭完全拉出至末端時，方可進行傾斜操作。</p> <p>向後推至中心以穩定並獲得更好的外觀。</p> </div> <p>燈具點亮使用時燈體外殼溫度較高注意燙手！</p>  
<p>5.</p>  <p>5. 在天花板上打螺絲並用螺絲鎖緊預埋框，預埋框外圍抹上水泥。</p>	<p>6.</p>  <p>6. 將電源線連接驅動輸入端，再將鋼索線掛鉤扣好本體。</p>	<p>7.</p>  <p>7. 將前罩卡入燈具內。</p>	<p>8.</p>  <p>8. 完成安裝，打開電源。</p>

設備名稱：LED嵌燈 ， 型號（型式）：RA-374RW-S50AH
 Equipment name Type designation (Type)

限用物質及其化學符號
 Restricted substances and its chemical symbols

單元 Unit	鉛Lead (Pb)	汞 Mercury (Hg)	鎘 Cadmium (Cd)	六價鉻 Hexavalent chromium (Cr ⁺⁶)	多溴聯苯 Polybrominated biphenyls (PBB)	多溴二苯醚 Polybrominated diphenyl ethers (PBDE)
金屬外殼	○	○	○	○	○	○
塑膠燈罩	○	○	○	○	○	○
線材	○	○	○	○	○	○
固定螺絲	○	○	○	○	○	○
彈簧夾	○	○	○	○	○	○
LED光源	○	○	○	○	○	○
驅動單元	超出0.1 wt %	○	○	○	○	○

備考1. “超出0.1 wt %”及“超出0.01 wt %”係指限用物質之百分比含量超出百分比含量基準值。

Note 1: “Exceeding 0.1 wt %” and “exceeding 0.01 wt %” indicate that the percentage content of the restricted substance exceeds the reference percentage value of presence condition.

備考2. “○”係指該項限用物質之百分比含量未超出百分比含量基準值。

Note 2: “○” indicates that the percentage content of the restricted substance does not exceed the percentage of reference value of presence.

備考3. “-”係指該項限用物質為排除項目。

Note 3: The “-” indicates that the restricted substance corresponds to the exemption.